

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4753</i>	LOCATION <i>7633 San Fernando</i>
DATE <i>7/6/40</i>	PURPOSE <i>Erect new dwg. &amp; gar</i>
ZONE	OWNER <i>Henry L. Reitz</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL <i>3000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
---------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>821<sup>01</sup></i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>304</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
9-12-40	1 <sup>st</sup> Lasp Forms of Joints
5/18-40	2 " Frame a Joints
	<div data-bbox="332 839 476 885" data-label="Text"> <p>COMPLETE AND O. K.</p> </div> <div data-bbox="1202 859 1353 890" data-label="Text"> <p>INSPECTOR</p> </div>