

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-1711</i>	LOCATION <i>1017 - 9th Street</i>			
DATE <i>6/1/34</i>	PURPOSE <i>Gen. Permit for Beaut. Phones</i>			
ZONE <i>Gen. Com</i>	OWNER <i>L. O. O. F. Hall Assoc.</i>			
	ARCH'T			
	CONT'R <i>W. B. - Ladue</i>			
VAL.	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
6/26/32	<p>Inspected Ramp built on heavy timbers and 2" plank on form below safe grades down to lot level. For Auto Parking Lot. Found same well braced and provided with walkways on each side.</p> <p style="text-align: right;">R.W. Campbell</p>
6/26/32	<p>COMPLETE AND O. K. <i>Walter H. Campbell</i> INSPECTOR</p>