

*R363 File 4/8*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**     \$5.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b>					
<i>G-3944</i>	<b>LOCATION</b>	<i>5341 - Spilman Avenue A-1 (1)</i>			
<b>DATE</b>	<b>PURPOSE</b>	<i>Const. open patio roof on rear of</i>			
<i>June-27-69</i>	<b>OWNER</b>	<i>Hugh Chally</i>	<i>Same</i>	<i>/dwelling</i>	
<b>ZONE</b>	<b>ARCH'T</b>				
<i>R-1</i>	<b>CONTR</b>	<i>Owner</i>	<i>Same</i>	<i>455-0389</i>	
<b>VAL.</b> <i>\$200.</i>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
					<i>140 sq. ft.</i>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>	
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	<i>8-18-69</i>	<i>Dana Fuller satis letter</i>			

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>