

2957 FJ30

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$20.00

TYPE BUILDINGS

Double Fee

PERMIT NO. G-2975	LOCATION 7056 - South Land Park Drive				A-3 (40)
DATE Apr. 2-69	PURPOSE	Repair fire damage to apartment bldg.			
ZONE R-1	OWNER	Hal Hewitt 916 - 21st Street			
	ARCH'T	444-0146			
	CONTR	Green Hill Const. 2520-J Street			
VAL. \$1,000.	STORIES 2	ROOMS	APTS.	SIZE	
INSP.	DATE	BLDG. TYPE	V-no hr.	OCCUPANCY GROUP	H-1 PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	12-11-69	Prolo			Ent

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK INSPECTOR