

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>4122-13</i>	LOCATION <i>1215 - Swanston St.</i>			
DATE <i>10/26/39</i>	PURPOSE <i>Erect new dwlg for</i>			
ZONE <i>V-7am</i>	OWNER <i>Land Dr. Tenacet Inc.</i>			
ARCH'T.	CONT'R. <i>C. C. Ruby.</i>			
VAL. <i>4500<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area</i>		
VENT SHAFTS	BOILER ROOMS	<i>1056<sup>sq</sup></i>		
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 350</i>		
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK-REMARKS
10/26/39	1 <sup>ST</sup> /NSP. Forms in place <sup>OK</sup> H. W. Campbell
11/16/39	2 <sup>ND</sup> /NSP. Frame " " <sup>OK</sup> H. W. Campbell
	<p data-bbox="284 865 415 906">COMPLETE AND O. K.</p> <p data-bbox="1126 880 1262 906">INSPECTOR</p>