

R225 F19A

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

5.00

TYPE BUILDINGS

| | | | | |
|------------------------|--------------------|---|--------------------|----------------------|
| PERMIT NO. F-8628 | LOCATION | 6988 13th Street | | A-3 |
| DATE Oct. 2/67 | PURPOSE | Const. roof & screen in exist. deck to OWNER R. Harold /rear of dwelling | | |
| ZONE R-1 | ARCH'T | 7410-Candlewood way / See F-8383 | | |
| | CONT'R | Len Taylor 2334-Cork Circle 428-4188 | | |
| VAL. \$200. | STORIES | ROOMS | APTS. | SIZE 170 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | |
| JOIST | | | | |
| FRAME SHEET ROCK | | | | |
| FINAL | <i>B. N. C. P.</i> | <i>[Signature]</i> | | <i>Police letter</i> |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |
| | INSPECTOR |