

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 111236</i>	LOCATION <i>316 - 18<sup>th</sup> Street</i>
DATE <i>7/24/43</i>	PURPOSE <i>Gen. Repair to interior dwlg.</i>
ZONE	OWNER <i>M. Nevis</i>
	ARCHT.
	CONTR. <i>Myron Westmore</i>

VAL. <i>2500<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

BLDG. DIV. PHOENIX, ARIZ. 1943

DATE	CONDITION OF WORK—REMARKS
8/9/43	2 <sup>nd</sup> floor. Frame. In Remodeling Kitchen & Rear Porch & installation addition of Windows in detail O. K. <i>W. Campbell</i>
8/9/43	3 <sup>rd</sup> floor. Patching of Plastering <sup>OK</sup> <i>W. Campbell</i>
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="305 878 427 916">COMPLETE AND O. K.</span> <span data-bbox="1113 890 1243 916">INSPECTOR</span> </div>