

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4596</i>	LOCATION <i>4020 - Miller Way</i>			
DATE <i>1/15/40</i>	PURPOSE <i>Remodel attic for bed room</i>			
ZONE	OWNER <i>D. G. Lindsay</i>			
	ARCH'T.			
	CONTR. <i>Universal Const. Co.</i>			
VAL. <i>1000.00</i>	STORIES <i>1</i>	ROOMS <i>2</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="309 849 443 896">COMPLETE AND O. K.</p> <p data-bbox="1155 865 1296 896">INSPECTOR</p>