







535 Carroll Ave.

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
535 Carroll Ave		535 Carroll Ave		6	
LEGAL DESCRIPTION					
Lot #23 Section 12 - Rancho Del Paso					
TITLE AND NAME		ADDRESS		TEL. NO.	
1/3 Claudia Williams		1413 North Ave		927-0465	
OWNER					
95838					
CERTIFICATE OF OCCUPANCY					
927-0465					
GEN. CONTR.		ELEC. CONTR.		PLUMBING BY	
Owner				DATE	
				1-24-78	
ELEC. CONTR.		MECH. CONTR.		MECHANICAL BY	
				DATE	
				1-24-78	
ARCH. ENGR.				DATE	
				1-24-78	
CONST. LOAN LENDER		1413 North Ave		927-0465	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
				NO. OF STORIES	
				1	
SIDE YARDS		REAR YARDS		SET BACK REQ.	
BLOG. WIDTH		BLOG. LENGTH		TOTAL HEIGHT	
				NO. OF STORIES	
				1	
ROOF CONSTR.		AREA 1st FLOOR		TOTAL AREA	
Comp		1615		C.S.D.	
C.I. CASE		CENSUS TRCT. NO.		EXISTING BLDG'S SAME LOT	
		1615			
HOW USED		TREES RMWD.		SPACES	
NO FINAL INSPECTION		NO FINAL INSPECTION		NO FINAL INSPECTION	

NATURE OF WORK: Const. Dwlg. 2/att gar & 144 sqs. ft. Patio Cover RDF #5164

7.00.88

PERMIT NO. S.P. -	C-9367	ISSUED BY	Overton
ISSUANCE DATE	11/13/75	PLANS AND APPLICATION	REEL NO. 593 TO 599
VALUATION	\$ 32,150.00	INSPECTION RECORD	REEL NO. 593 TO 599
R.D.F. FEE	\$ 158.00	JOB FILE	REEL NO. TO
S.M.I. FEE	\$ 2.31	PLAN CK. FEE	\$
SEWER INCL. FEE	\$	PERMIT FEE	\$ 222.00
TOTAL FEES	\$ 382.31	REMARKS AND/OR VARIANCES	

000659 X45