

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD *Value 20 Way*

TYPE BUILDINGS

0-10-11

PERMIT NO. <i>B-20086</i>	LOCATION <i>725 - Lutter Way</i>			
DATE <i>9-24-47</i>	PURPOSE <i>Erect dwlg + garage</i>			
ZONE	OWNER <i>W. Pierce</i>			
	ARCH'T.			
	CONTR. <i>J. Fernandez</i>			
VAL. <i>\$5250</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK-REMARKS
4/5/47	Form Insp. D. E. Buckins
12/11/47	FRAME " R. E. Jones
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>