

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-2457</i>	LOCATION <i>3928 - 3930 - Milly Way</i>			
DATE <i>12/27/38</i>	PURPOSE <i>Erect new duplex</i>			
ZONE	OWNER <i>Jim Lisicki</i>			
	ARCH'T.			
	CONTR. <i>Universal Const. Co.</i>			
VAL. <i>6000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>8</i>	APTS. <i>2</i>	SIZE
LIGHT SHAFTS				ELEVATOR SHAFTS <i>1582<sup>01</sup></i>
VENT SHAFTS				BOILER ROOMS <i>@ 350</i>
OWNER'S INSPECTOR				SPRINKLER SYSTEM
LATH				GAS VENTS
FIRE ESCAPES				CHIMNEYS
STAND PIPES				SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
1-4-39	15' Jump <del>to</del> <sup>to</sup> frame of <del>Route</del> <sup>Route</sup>
2-6-39	2 " frame & Route
2-7-39	3 " Lath <del>at</del> <sup>at</sup> Route
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="279 850 407 891">COMPLETE AND O. K.</span> <span data-bbox="1134 866 1267 888">INSPECTOR</span> </div>