

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2457</i>	LOCATION <i>3928 - 3930 - Milly Way</i>			
DATE <i>12/27/38</i>	PURPOSE <i>Erect new duplex</i>			
ZONE	OWNER <i>Jim Lisicki</i>			
	ARCH'T.			
	CONTR. <i>Universal Const. Co.</i>			
VAL. <i>6000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>8</i>	APTS. <i>2</i>	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS		<i>1582⁰¹</i>	
VENT SHAFTS	BOILER ROOMS		<i>@ 350</i>	
OWNER'S INSPECTOR	SPRINKLER SYSTEM			
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK-REMARKS
1-4-39	1 st Jump to ^{to} frame ^{of} Route ^{Route}
2-6-39	2 " frame & Route
2-7-39	3 " Lath Street Route
	<p data-bbox="279 855 404 891">COMPLETE AND O. K.</p> <p data-bbox="1137 866 1264 891">INSPECTOR</p>