

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11007-</i>	LOCATION <i>3441 - San Carlos</i>			
DATE <i>12/30/42</i>	PURPOSE <i>Reconst. crane</i>			
ZONE	OWNER <i>Mrs. Smith</i>			
	ARCH'T.			
	CONTR. <i>H. G. Hendren</i>			
VAL. <i>1900=</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE.	CONDITION OF WORK-REMARKS
1/19/43	<p>1-Car Frame Private Garage re built to replace original one recently destroyed by fire. Re-used Cor. Iron on both sides and installed new foundation walls to replace original foundation built below Cement Floor</p> <p style="text-align: right;">OK →</p>
1/19/43	<p>COMPLETE AND O. K. <i>Allen J. Campbell</i> INSPECTOR</p>