

1
237 2536-541

Portion of
 Lot 6 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$73.00

A. & B. Davis
 Homestead Tract TYPE BUILDINGS *R251 F57D full*

PERMIT NO. G-290 LOCATION 2836 - Redding Avenue A-1 (17)

DATE May 8-68 PURPOSE Const. office in warehouse
 OWNER John & Doris Hattel Same

ZONE M-1 ARCH'T Ken Venolia 5709 - Freeport Blvd.
 CONT'R Chas. F. Unger Const. 2112-Suttervill

VAL \$22,000.	STORIES 1	ROOMS	APTS.	SIZE 2,910 sq. ft.
---------------	-----------	-------	-------	--------------------

INSP.	DATE	BLDG. TYPE V no hr.	OCCUPANCY GROUP F-2	PHONE (O) IC 452-1458
-------	------	---------------------	---------------------	-----------------------

FORM *6-5-68* *Boyle*

JOIST

FRAME *7-23-68* *Barbato*

SHEET ROCK

FINAL *8-29-68* *J. Barbato* *[Signature]*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
6-3-68	Ft. Smith, Ark. Not ready. <i>Kudo</i>
6-5-68	No work. <i>Kudo</i>
6-10-68	BB called - unable to make. <i>Kudo</i>
6-11-68	Pl 4 BB. <i>Kudo</i>
6-12-68	Pl 8 - BB. <i>Kudo</i>
6-13-68	Pl 12 - BB. <i>Kudo</i>
6-14-68	Pl 16 BB N.S.W. <i>Kudo</i>
6-17-68	BB called, unable to make. <i>Kudo</i>
6-19-68	Pl 22 - BB - unable to make. <i>Kudo</i>
7-23-68	Pl was rail. <i>Kudo</i>
8-14-68	Pl SR, no job card. kept note to call back. <i>Kudo</i>
10-10-68	Pl 43 - image not parameter. <i>Kudo</i>
10-14-68	Training of drainage, intensive. <i>Kudo</i>
11-18-68	Pl 43 - image not parameter. <i>Kudo</i>
	<i>Kudo</i>
	COMPLETE AND OK
	INSPECTOR