

*R279 E366*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

\$15.00

**TYPE BUILDINGS**

PERMIT NO. <b>G-6448</b>		LOCATION <b>708 - Santa Ynez Way A-1 (15)</b>			
DATE <b>Apr. 15-70</b>		PURPOSE <b>Repair pest damage to dwelling</b>			
ZONE <b>R-1</b>		OWNER <b>Estate of Ruby E. Carter</b>			
		ARCH'T			
		CONTR <b>Sacramento Termite Control 1601-Fulton</b>			
VAL. <b>\$1,100.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM	<i>4-23-70</i>	<i>Wood</i>			<b>482-8800</b>
JOIST					
FRAME	<i>4-23-70</i>	<i>Wood</i>			
SHEET ROCK					
FINAL	<i>5-28-70</i>	<i>[Signature]</i>			

DATE	SPECIAL CONDITIONS OF WORK-- REMARKS
	<p data-bbox="340 833 468 885"><b>COMPLETE AND OK</b></p> <p data-bbox="1171 854 1300 885"><b>INSPECTOR</b></p>