

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS	
		681 Brickyard Drive				A-3		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE
Basford Estates #1 Lot 28								
TITLE AND NAME		1/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.	BUILDING BY	DATE
owner			same				Riolo	7-2-73
GEN. CONTR.							ELECTRICAL BY	DATE
ELEC. CONTR.							PLUMBING BY	DATE
PLBG. CONTR.							MECHANICAL BY	DATE
MECH. CONTR.								
ARCH. ENGR.								
OWNER	Lee Basford		6660 Havenside Drive			CERTIFICATE OF OCCUPANCY		
CONST. LOAN LENDER						ISSUED BY		DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE
						2342 sq ft	CENSUS TRCT. NO.	
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED
			R-1					

NATURE OF WORK:- Const dwelling and att gar

PERMIT NO. S.P. - H-9569	MICROFILM RECORD		
ISSUED BY	PLANS AND APPLICATION	REEL NO. 339	FRAME NO:- 537 TO 545
ISSUANCE DATE 11-20-72	INSPECTION RECORD	REEL NO. 11007	FRAME NO:- 1007 TO 1008
VALUATION \$ 35,200.	JOB FILE	REEL NO.	FRAME NO:- TO
R.D.F. FEE \$			
S.M.I. FEE \$			
PLAN CK. FEE \$			
SEWER INCL. FEE \$			
PERMIT FEE \$ 120.50	REMARKS AND/OR VARIANCES		
\$	form 12-6-72 Riolo		
\$	joist 12-19-72 "		
\$	frame 2-6-73 "		
TOTAL FEES \$	sheet rock 2-14-73 Riolo		

