

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS			
		681 Brickyard Drive				A-3				
LEGAL DESCRIPTION				OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE	
Basford Estates #1 Lot 28								Riolo	7-2-73	
TITLE AND NAME		1/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY		DATE	
owner			same							
GEN. CONTR.									PLUMBING BY	DATE
owner										
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.									CERTIFICATE OF OCCUPANCY	
									ISSUED BY	DATE
MECH. CONTR.										
ARCH. ENGR.										
OWNER		6660 Havenside Drive								
Lee Basford										
CONST. LOAN LENDER										
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
						2342 sq ft				
							CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		
			R-1							

NATURE OF WORK:- Const dwelling and att gar

PERMIT NO. S.P.	H-9569	MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE	11-20-72	PLANS AND APPLICATION	REEL NO.	339	FRAME NO:- 537 TO 545
VALUATION	\$ 35,200.	INSPECTION RECORD	REEL NO.	11007	FRAME NO:- 1007 TO 1008
R.D.F. FEE	\$	JOB FILE	REEL NO.		FRAME NO:- TO
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$ 120.50	REMARKS AND/OR VARIANCES			
	\$	form 12-6-72 Riolo			
	\$	joist 12-19-72 "			
	\$	frame 2-6-73 "			
TOTAL FEES	\$	sheet rock 2-14-73 Riolo			

