

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3134</i>	LOCATION <i>433 - San Antonio St</i>			
DATE <i>5/23/39</i>	PURPOSE <i>Erect new dwl. & gar</i>			
ZONE <i>1</i>	OWNER <i>Anton Norcia</i>			
	ARCH'T. <i>J. C. Hansen</i>			
	CONT'R. <i>J. C. Hansen</i>			
VAL. <i>3500⁰⁰</i>	STORIES <i>0/1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>962⁰¹</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>© 350</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
5/28-39	1 st Jump Frames on Quarter
7/30-39	2 nd Jump Frames on Quarter
7/15-39	3 " Lark JTBK Quarter

COMPLETE
AND O. K.

INSPECTOR