

Lot #80		BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD			R-59 F733-738
S.L.P. Hills #21		TYPE BUILDINGS			\$47.00
PERMIT NO. D-3015	LOCATION	1319 - <del>58th Avenue</del> Palomar Circle			A-3
DATE Aug. 21-59	PURPOSE	Const. duplex & garage			
	OWNER	L. Abern & Seill Berger			
ZONE R-1	ARCH'T				
	CONT'R	Robert McCormick	YO 7-0956		
VAL. \$18,600.	STORIES 1	ROOMS 11	APTS.	SIZE 2000 Sq.ft.	
INSP.	DATE	INSPECTOR			
FORM	9-1-59	Jones			
JOIST	9-16-59	Shumway			
FRAME	10-29-59	Calloway			
LATH	11-23-59	M Calloway			
FINAL	2-25-60	Court			

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
10-27-59	P.T. Improper fire walls. Holes in vapor barrier. Framing around washing machine. Plumbing wrong. Improper blocking. Loose + missing fire blocks. + other misc. code viod. Jones.
10-29-59	P.T. P.P. Construction. Calloway
11-18-54	P.T. Top fire wall broke on studs
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="310 921 455 972">COMPLETE AND OK</span> <span data-bbox="1270 947 1421 972">INSPECTOR</span> </div>