

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>49955</i>	LOCATION <i>57 Land Drive Newark 1119 Perkins Way</i>
DATE <i>4/27/51</i>	PURPOSE <i>FR. SN. 4 1/2 ST. DR. GARAGE</i>
ZONE <i>2A</i>	OWNER <i>Land Drive Newark</i>
	ARCH'T <i>[Signature]</i>
	CONT-R <i>[Signature]</i>

PHONES

VAL. <i>4150</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS. <i>1</i>	SIZE <i>36x35-30</i>
---------------------	---------------------	-------------------	-------------------	-------------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
4/28-31	1 st Imp Forms OK P. H. Rutter
5/14-31	2 nd Frame " P. H. Rutter
5/18/31	3 rd HSP. INT & EXT LATH IN PLACE ^{OR} A. H. Campbell
7/10-31	4 th " Gmaled & ON Certificate of
	occupancy issued ON
	A. C. up
COMPLETE AND O.K.	<div data-bbox="520 834 1184 991" data-label="Text"> <p>P. H. Rutter</p> </div>
	INSPECTOR