

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-4523</i>	LOCATION <i>440 - San Antonio Way</i>			
DATE <i>7/2/36</i>	PURPOSE <i>Erect new duplex garage</i>			
ZONE <i>2-Fam.</i>	OWNER <i>Klein Realty Co.</i>			
	ARCH'T. <i>[Signature]</i>			
	CONTR. <i>Klein Realty Co. 807-928</i>			
VAL. <i>3700⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS. <i>2</i>	SIZE <i>duplex</i>
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 1064</i>	
VENT SHAFTS		BOILER ROOMS	<i>@ 3,50</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
7/5-36	1 st Insp Forms of Inspector
8/4 "	2 nd Frame of Inspector
8/10/36	3 rd Insp. EXT LATH ^{OK} AW Campbell

COMPLETE
AND O. K.

INSPECTOR