

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

| | |
|---------------------------|----------------------------------|
| PERMIT NO. <i>1044</i> | LOCATION <i>1021-10th</i> |
| DATE <i>1935</i> | PURPOSE <i>Begin Vertical</i> |
| SA ZONE <i>AUC</i> | OWNER <i>Dr. Simmons</i> |
| | ARCH'T <i>Walter B...</i> |
| | CONT'R <i>Walter B...</i> |

| | | | | |
|---------------------|---------|-------|-------|------|
| VAL. <i>600.</i> | STORIES | ROOMS | APTS. | SIZE |
|---------------------|---------|-------|-------|------|

| | | | |
|-------------------------------|--|------------------|--|
| Steel Tested by | | Elevator Shafts | |
| Cement Tested by | | Boiler Rooms | |
| Owner's Inspector Rfcd. Conc. | | Sprinkler System | |
| | | Floor Tests | |
| Fire Escapes | | | |
| Stand-pipes | | | |

APPROVED FOR THE CITY OF CHICAGO

DATE

CONDITION OF WORK--REMARKS

COMPLETED
AND O. K.

Inspector