

2176 F132

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

PERMIT NO. F-1560	LOCATION 3875 - 4th Avenue	A-1		
DATE Aug 24-65	PURPOSE Repair auto damage to porch			
ZONE R-1	OWNER McClendon Washington	same		
	ARCH'T			
	CONT'R	Owner same		
VAL \$1,000.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM				
JOIST	10-13-65	Chapin		
FRAME	12-26-65	Chapin		
SHEET ROCK	11-5-65	Chapin		
FINAL	10/10/66	Dona E. Fuller		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-11-65	D.J. joint - 11cf ready Chapin
	10-31-65 Pt frame - Propping & siding not on Chapin
5	<p style="text-align: center;">COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>