

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3553</i>	LOCATION <i>974 - Perkins Way</i>
DATE <i>8/1/34</i>	PURPOSE <i>New dwlg. - gar</i>
ZONE	OWNER <i>Wm A. Daniels</i>
	ARCH'T.
	CONT'R. <i>John Fernandez</i>

VAL. <i>4500.00</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
---------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1245 sq ft</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>0350</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
8-8-39	1 st Insp Forms in place of Ruster
8/27/39	2 nd Insp. Frame in place ^{OK} A W Campbell
9/15/39	3 rd Insp. Int & Ext Latic ^{OK} A W Campbell
11/9/39	4 th Insp. Driv & Garage Completed
	Issued Final Insp. & Cert. of Occy.
	Street Cleared up OK
11/9/39	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O. K. Alden W Campbell INSPECTOR </div>