

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-1877</i>	LOCATION <i>3162 - Penna. Way</i>			
DATE <i>7/31/36</i>	PURPOSE <i>Gen. Repair to develop interior.</i>	PHONES		
ZONE <i>Mult. Fam</i>	OWNER <i>Geo. Dexter Sims</i>			
	ARCH'T			
	CONT'R <i>Frank Malone</i>			
VAL. <i>1695⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
	2 ND / WSP (Partial Frame) for rear part of
	Duly damaged by fire
	O.K. R.W. Campbell
8/7/34	2 ND / WSP. Bot. of Frame for general repairs
	to duly damaged by fire
	O.K. R.W. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O.K. INSPECTOR </div>