

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-1877</i>	LOCATION <i>3162 - Penna. Way</i>		
DATE <i>7/31/36</i>	PURPOSE <i>Gen. Repair to develop interior.</i>	PHONES	
ZONE <i>Mult. Fam</i>	OWNER <i>Geo. Dexter Sims, I</i>		
	ARCH'T		
	CONT'R <i>Frank Malone</i>		
VAL. <i>1695<sup>00</sup></i>	STORIES	ROOMS	APTS. <i>1</i>
			SIZE
Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
	2 <sup>ND</sup> / WSP (Partial Frame) for rear part of
	Duly damaged by fire
	O.K. R.W. Campbell
8/7/34	2 <sup>ND</sup> / WSP. Bot. of Frame for general Repairs
	to duly damaged by fire
	O.K. R.W. Campbell
	COMPLETE AND O.K. INSPECTOR