

R 288 F119

| | | | | |
|---|--------------------------------|--|-----------------|-----------------------------------|
| Lot 1169 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$68.00 | | | | |
| Glenbrook Unit No. 11 TYPE BUILDINGS R-282 F-53-57 Plans | | | | |
| PERMIT NO. G-8249 | LOCATION 65 - Moss Glen Circle | | A-1 (52) | |
| DATE 9-8-70 | PURPOSE | Construct dwelling & garage | | MP 1003 B |
| ZONE R-1 | OWNER | Barbrook, Inc, 2777 Alvarado St, San Leandro | | |
| | ARCH'T | Leandro | | |
| | CONTR | Besco Builders, Same as owner | | |
| VAL. \$17,100. | | STORIES | ROOMS | APTS. 480-gar. SIZE 1,100-sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) 383-9315 |
| FORM | 9-25-70 | <i>[Signature]</i> | | |
| JOIST | | | | |
| FRAME | 10-22-70 | <i>[Signature]</i> | | |
| SHEET ROCK | 10-27-70 | <i>[Signature]</i> | | |
| FINAL | 11-24-70 | Dana E. Fuller | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---|
| 9.24.70 | Pk frame - not busy <i>Callaway</i> |
| 9.24.70 | Pk cont <i>Summers</i> |
| 9.30.70 | Pk frame - not busy <i>Teller</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="289 819 412 871">COMPLETE AND OK</p> <p data-bbox="1136 847 1263 871">INSPECTOR</p> |