

**CITY OF SACRAMENTO**  
1231 I Street, Sacramento, CA 95814

**Permit No: 0006114**  
**Insp Area: 2**

**Site Address: 1408 7TH AV SAC**  
Parcel No: 012-0292-008

Sub-Type: RES  
Housing (Y/N): N

CONTRACTOR  
BOULEY PEST CONTROL  
3639 4TH AV  
SAC TO CA 95817

OWNER  
PETERSEN ROBERT J & MARIETTA  
1408 7TH AV  
SACRAMENTO CA 95818

ARCHITECT

**Nature of Work: DRY ROT REPAIR & MINOR PLUMBING**

**CONSTRUCTION LENDING AGENCY :** I hereby affirm under penalty of perjury that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civ. C).

Lender's Name \_\_\_\_\_ Lender's Address \_\_\_\_\_

**LICENSED CONTRACTORS DECLARATION:** I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter 9 (commencing with section 7000) of Division 3 of the Business and Professions Code and my license is in full force and effect.

License Class \_\_\_\_\_ License Number PR2375 Date 6/6/00 Contractor Signature Boley Pest Control

**OWNER-BUILDER DECLARATION:** I hereby affirm under penalty of perjury that I am exempt from the contractors License Law for the following reason (Sec. 7031.5, Business and Professions Code; any city or county which requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he or she is licensed pursuant to the provisions of the Contractors License Law (Chapter 9 (commencing with Section 7000) of Division 8 of the Business and Professions Code) or that he or she is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more than five hundred dollars (\$500.00):

\_\_\_\_ I, as a owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business and Professional Code: The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who does such work himself or herself or through his/her own employees, provided that such improvements are not intended or offered for sale. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he/she did not build or improve for the purpose of sale.)

\_\_\_\_ I, as owner of the property, am exclusively contracting with licensed contractors to construct the project (Sec. 7044, Business and Professions Code: The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who contracts for such projects with a contractor(s) licensed pursuant to the Contractors License Law).

\_\_\_\_ I am exempt under Sec. \_\_\_\_\_ B & PC for this reason: \_\_\_\_\_

Date \_\_\_\_\_ Owner Signature \_\_\_\_\_

**IN ISSUING THIS BUILDING PERMIT,** the applicant represents, and the city relies on the representation of the applicant, that the applicant verified all measurements and locations shown on the application or accompanying drawings and that the improvement to be constructed does not violate any law or private agreement relating to permissible or prohibited locations for such improvements. This building permit does not authorize any illegal location of any improvement or the violation of any private agreement relating to location of improvements.

I certify that I have read this application and state that all information is correct. I agree to comply with all city and county ordinances and state laws relating to building construction and hereby authorize representative(s) of this city to enter upon the above mentioned property for inspection purposes.

Date 6/6/00 Applicant/Agent Signature RP Boley Pest Control

**WORKER'S COMPENSATION DECLARATION:** I hereby affirm under penalty of perjury one of the following declarations:

~~I have and will maintain a certificate of consent to self-insure for workers' compensation as provided for by Section 3700 of the Labor Code, for the performance of work for which the permit is issued.~~

~~I have and will maintain workers' compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. My workers' compensation insurance carrier and policy number are:~~

Carrier Sedgwick JAMES INS. BROKERS Policy Number #S-9982117208 Exp Date 10/01/00

\_\_\_\_ (This section need not be completed if the permit is for \$100 or less) I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workers' compensation laws of California and agree that if I should become subject to the workers' compensation provisions of Section 3700 of the Labor Code, I shall forthwith comply with those provisions.

Date 6/6/00 Applicant Signature RP Boley Pest Control

**WARNING: FAILURE TO SECURE WORKER'S COMPENSATION COVERAGE IS UNLAWFUL AND SHALL SUBJECT AN EMPLOYER TO CRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000) IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST AND ATTORNEY'S FEE.**

**THIS PERMIT SHALL EXPIRE BY LIMITATION IF WORK IS NOT COMMENCED WITHIN 180 DAYS.**

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

This is an inspection report only - not a Notice of Completion

## ADDRESS OF PROPERTY INSPECTED

BUILDING NO: 1408	STREET: 7th Avenue	CITY: Sacramento	ZIP: 95818	COUNTY CODE: 34	DATE OF INSPECTION: 05/10/2000	NUMBER OF PAGES: 5
----------------------	-----------------------	---------------------	---------------	--------------------	-----------------------------------	-----------------------

### BOUEY PEST CONTROL

**3639 4TH AVENUE  
SACRAMENTO CA 95817**  
Tel (916) 733-0520 Fax (916) 733-0529 Alt

Affix stamp here on Board copy only  
**A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.**

REGISTRATION # FR 2375	REPORT # 10925	STAMP #	ESCROW #
---------------------------	-------------------	---------	----------

ORDERED BY: Marietta Petersen - 8952 Four Seasons Drive, Elk Grove, CA 95624


REPORT SENT TO: \_\_\_\_\_

PROPERTY OWNER: Marietta Petersen - Above

PARTY IN INTEREST: Lyon & Assoc. Realtors - Karin Libbee FAX# 447-4051

ORIGINAL REPORT <input checked="" type="checkbox"/>	LIMITED REPORT <input type="checkbox"/>	SUPPLEMENTAL REPORT <input type="checkbox"/>	REINSPECTION REPORT <input type="checkbox"/>	#Original Stamp #	Date:									
GENERAL DESCRIPTION: <u>1 Story frame residence - wood and stucco siding with shake roofing</u>		IN ACCESSIBLE AREAS	NOT INSPECTED	FURTHER INSPECTION	SUBTERRANEAN TERMITES	DRYWOOD TERMITES	FUNGUS OR DRY ROT	OTHER WOOD PESTS	DAMPWOOD TERMITES	EARTHWOOD CONTACT	FAULTY GRADE LEVELS	CELLULOSE DEBRIS	EXCESSIVE MOISTURE	SHOWER LEAKS
INSPECTION TAG POSTED: <u>Subarea</u>														
OTHER INSPECTION TAGS:														
1. SUBSTRUCTURE AREAS:	<u>Dry, accessible, See #1</u>							X	X					
2. SHOWER STALL:	<u>Tested, leakage, See #2</u>											X		
3. FOUNDATIONS:	<u>Raised concrete</u>													X
4. PORCHES - STEPS:	<u>Concrete appears sealed</u>													
5. VENTILATION:	<u>Appears adequate</u>													
6. ABUTMENTS:	<u>None</u>													
7. ATTIC SPACES:	<u>Limited due to insulation</u>													
8. GARAGES:	<u>Not inspected</u>													
9. DECKS - PATIOS:	<u>Patio, inspected, See #9</u>													
10. OTHER - INTERIOR:	<u>Inspected, See #10</u>			X						X	X			
11. OTHER - EXTERIOR:	<u>Inspected, See #11</u>							X						

DIAGRAM AND EXPLANATION OF FINDINGS (This is limited to structure or structures shown on diagram)  
DIAGRAM NOT TO SCALE



FRONT

Inspected By: Keith L. Pardee License No. FR 28790 Signature: Keith Pardee

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 262-2823, or (800) 737-9168. You are entitled to obtain copies of all reports and completion notices on this property filed with the Board during the preceding two year upon payment of a \$2.00 search fee to: The Structural Pest Control Board, 1415 Howe Ave. Suite 16, Sacramento, California, 95825-3288.

# BOUEY PEST CONTROL

Page 3 of 5 of Standard Inspection Report

1408 7th Avenue Sacramento CA 95818  
Address of Property Inspected City State Zip  
Stamp No. 5/10/2000 10925 Escrow No.  
Date of Inspection Co. Report No.

\*NOTICE\* The Structural Pest Control Board encourages competitive business practices among registered companies should list the same findings, (i.e.-termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

Under the California Mechanics Lien Law, any Structural Pest Control Operator who contracts to do work for any contractor, subcontractor, laborer, supplier, or other person who helps to improve your property but has not been paid for his work or supplies, has a right to enforce a claim against your property. This means that after a hearing, your property could be sold by a court office and the proceeds of the sale used to satisfy the debt. This can happen even if you paid your contractor in full if the subcontractor, laborers, or suppliers remain unpaid. We reserve the right to file a claim or lien against your property. Certain claimants, such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". General contractors and laborers for wages do not provide this notice. A "Preliminary Notice" is not a lien against the property. Its purpose is to notify you of persons who may have a right to file a lien against your property for debts that are not paid.

Bouey Pest Control cannot certify the roof nor do we offer any opinion as to its' quality.

The exterior surface of the roof will not be inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

Most exposed areas repaired will be painted or primed with one (1) coat of paint or primer. No guarantee is given on color match or quality of painting.

If damage extends into inaccessible areas, a Supplemental Inspection will be made and Report issued outlining our findings, recommendations, and additional cost.

This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection. Section I contains items where there is visible evidence of active infestation, infection or conditions that have resulted in or from infestation of infection. Section II items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section I or Section II.

Bouey Pest Control does not inspect tub and shower enclosures for water tightness.

## 1 SUBSTRUCTURE

FINDING 1A: Cellulose debris noted in the subarea.

RECOMMENDATION 1A: Remove cellulose debris.

SECTION 2.

# BOUEY PEST CONTROL

Page 4 of 5 of Standard Inspection Report

1408 7th Avenue Sacramento CA 95818  
Address of Property Inspected City State Zip  
Stamp No. 5/10/2000 10925 Escrow No.  
Date of Inspection Co. Report No.

FINDING 1B: Evidence of wood boring beetle infestation and damage noted in subfloor.

RECOMMENDATION 1B: Vacate and seal the house. Fumigate with the registered fumigant Vikane (sulfuryl fluoride) for furnished structures, or Methyl Bromide (methyl bromide) for unfurnished structures, or beetle infestation only. Chloropicrin to be used as the warning agent. Refer to your posted re-entry notice for the actual fumigant used. Please note effect of over-exposure from these materials can include the following: shortness of breath, double vision, unusual drowsiness, weakness, and tremors. Your health and safety are our major concern. If you experience the symptoms as outlined here, leave the structure immediately and call our office.

Remove the seals and aerate the structure ready for occupancy.

Prior to the fumigation process, certain preparations must be made. Please refer to our "Occupants' Fumigation Notice and Instruction Sheet" for specific guidelines. Preparations per these instructions is not the responsibility of Bouey Pest Control.

The fumigation cannot be done in strong winds or rain and will be rescheduled if there is inclement weather.

The fumigation process requires that work crews walk on the roof. Many roofs are brittle and suffer some damage when walked on. The Company will not be responsible for damage resulting from walking or working on the roof, or for any damage to any of the following items: any roofing surface; radio and television antennas; plants which are clinging or very close to the structure; awnings; gutters; patio covers; solar heating panels; plumbing fixtures; or any other items on, or connected to, the roof, including chimneys.

Bouey Pest Control does not provide on-site security and does not assume any responsibility for the care and custody of the property in the event of vandalism or breaking and entering. Bouey Pest Control requests that all valuables, such as jewelry, coins, collections, cash, art objects, and other items of value, be removed prior to fumigation. Brace and mask subfloor.  
SECTION 1.

FINDING 1C: Fungus infection and damage noted in subfloor and joists at hall shower. Leakage noted. Sections of subfloor are missing.

RECOMMENDATION 1C: Remove and replace sections of subfloor and joists. See 2A on shower repairs.  
SECTION 1.

## 2 SHOWER

FINDING 2A: Hall stall shower water tested and leakage noted at subarea.  
RECOMMENDATION 2A: Remove tile from the shower floor and base of the walls. Install new water-proof pan and retile with blending colors.

If damage is found in framing after removal of tile, or plumbing requiring repair is disclosed, a Supplemental Inspection will be made and Report issued outlining our findings, recommendations, and additional cost. New tiles will not match existing.  
SECTION 1.

## 7 ATTIC

\*7 NOTE\* Attic area is inaccessible for inspection due to insulation concealing the ceiling joists which prevents safe passage. Due to hazardous footing, our inspection is limited to the areas visible from the attic access opening only.

# BOUEY PEST CONTROL

Page 5 of 5 of Standard Inspection Report

1408	7th Avenue	Sacramento	CA	95818
Address of Property Inspected		City	State	Zip
	5/10/2000	10925		
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.	

## 9 PATIO

FINDING 9A: Faulty grade level and earth-wood contact noted at patio wing wall.

RECOMMENDATION 9A: Lower soil away from bottom of siding.

SECTION 2.

## 10 INTERIOR

FINDING 10A: Various windows were painted and stuck closed. Inaccessible areas not inspected.

RECOMMENDATION 10A: Open painted and stuck closed window when repairs are in progress for further inspection. If infestations or infections are found, a Supplemental Inspection will be made and Report issued outlining our findings, recommendations, and additional cost.

SECTION 2.

## 11 EXTERIOR

FINDING 11A: Fungus infection and damage noted in bottom of 6x6 post.

RECOMMENDATION 11A: Remove and replace post.

SECTION 1.

FINDING 11B: Dryrot noted at bottom of corner trim and foundation vent trim.

RECOMMENDATION 11B: Remove and replace section of trim at vent. Trim off dryrot at corner trim.

SECTION 1.

# BOUEY PEST CONTROL

3639 4TH AVENUE  
SACRAMENTO CA 95817  
Tel (916) 733-0520 Fax (916) 733-0529 Alt

## AGREEMENT

No work will be performed until a signed copy of this agreement has been received.

Address of Property: 1408 7th Avenue  
City: Sacramento  
State/Zip: CA 95818

The inspection report of the company dated, 5/10/2000 bearing the Structural Pest Control Board Stamp Number, \_\_\_\_\_ is incorporated herein by reference as though fully set forth.

The company is authorized to proceed with the work outlined in the items droled below from the Termite Inspection Report for the property inspected, for a total sum of \$ \_\_\_\_\_. This total amount is due and payable within Ten (10) days from completion repair work and/or chemical application.

### THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting or plumbing, which is guaranteed for a period of Ninety (90) days. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants or roof.

### THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The Owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

### ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

### NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control operator who contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his work or supplies, has a right to enforce a claim against your property. This means that after a court hearing your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your contractor in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". General contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

## ITEMS

SECTION 1 ITEM(S) #	1B.....\$ 1595.00	SECTION 2 ITEM(S) #	1A.....\$ 45.00
	1C.....\$ 610.00		9A.....\$ 20.00
	2A.....\$ 1520.00		10A.....\$ 50.00
	11A.....\$ 90.00		
	11B.....\$ 45.00		
		TOTAL...\$	115.00
TOTAL...\$	3860.00		

\*MINIMUM JOB PRICE...\$ 190.00\*

Property Owner: \_\_\_\_\_

Date: \_\_\_\_\_

Inspected By: Kathleen

Date: \_\_\_\_\_

Owner's Agent: \_\_\_\_\_

Date: \_\_\_\_\_

No. 5664 P. 8

Jun. 5. 2000 1:52PM BOUEY PEST CONTROL

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

This is an Inspection report only - not a Notice of Completion

## ADDRESS OF PROPERTY INSPECTED

BUILDING NO: 1408	STREET: 7th Avenue	CITY: Sacramento	ZIP: 95818	COUNTY CODE: 34	DATE OF INSPECTION: 06/01/2000	NUMBER OF PAGES: 3
----------------------	-----------------------	---------------------	---------------	--------------------	-----------------------------------	-----------------------

### BOUEY PEST CONTROL

**3639 4TH AVENUE  
SACRAMENTO CA 95817**  
Tel (916) 733-0520 Fax (916) 733-0529 Alt

Affix stamp here on Board copy only  
**A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.**

REGISTRATION # PR 2375	REPORT # 11112	STAMP #	ESCROW #
---------------------------	-------------------	---------	----------

ORDERED BY: Bob & Marietta Petersen - 8952 Four Seasons Dr., Elk Grove, CA 95624


REPORT SENT TO: \_\_\_\_\_

PROPERTY OWNER: Bob & Marietta Petersen - Above

PARTY IN INTEREST: Lyon & Assoc. Realtors - Karin Libbee FAX# 447-4051

ORIGINAL REPORT <input type="checkbox"/>	LIMITED REPORT <input type="checkbox"/>	SUPPLEMENTAL REPORT <input type="checkbox"/>	REINSPECTION REPORT <input checked="" type="checkbox"/>	Original Stamp #	Date:
GENERAL DESCRIPTION:  INSPECTION TAG POSTED:  OTHER INSPECTION TAGS:	1. SUBSTRUCTURE AREAS: 2. SHOWER STALL: 3. FOUNDATIONS: 4. PORCHES - STEPS: 5. VENTILATION: 6. ABUTMENTS: 7. ATTIC SPACES: 8. GARAGES: 9. DECKS - PATIOS: 10. OTHER - INTERIOR: 11. OTHER - EXTERIOR:	IN ACCESSIBLE AREAS NOT INSPECTED FURTHER INSPECTION SUBTERRANEAN TERMITES DRYWOOD TERMITES FUNGUS OR DRY ROT OTHER WOOD PESTS DAMPWOOD TERMITES EARTHWOOD CONTACT FAULTY GRADE LEVELS CELLULOSE DEBRIS EXCESSIVE MOISTURE SHOWER LEAKS			

DIAGRAM AND EXPLANATION OF FINDINGS (This is limited to structure or structures shown on diagram)  
DIAGRAM NOT TO SCALE



FRONT

Inspected By: Keith L. Pardee License No. FR 28790 Signature: *Keith Pardee*

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Uninvolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 263-2635, or (800) 737-8188. You are entitled to obtain copies of all reports and completion notices on this property filed with the Board during the preceding two year upon payment of a \$2.00 search fee to: The Structural Pest Control Board, 1418 Howe Ave., Suite 18, Sacramento, California, 95826-3280.

# BOUEY PEST CONTROL

Page 3 of 3 of Standard Inspection Report

1408	7th Avenue	Sacramento	CA	95818
Address of Property Inspected		City	State	Zip
Stamp No.	6/1/2000	11112	Escrow No.	
	Date of Inspection	Co. Report No.		

\*NOTICE\* The Structural Pest Control Board encourages competitive business practices among registered companies should list the same findings, (i.e.-termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

Under the California Mechanics Lien Law, any Structural Pest Control Operator who contracts to do work for any contractor, subcontractor, laborer, supplier, or other person who helps to improve your property but has not been paid for his work or supplies, has a right to enforce a claim against your property. This means that after a hearing, your property could be sold by a court office and the proceeds of the sale used to satisfy the debt. This can happen even if you paid your contractor in full if the subcontractor, laborers, or suppliers remain unpaid. We reserve the right to file a claim or lien against your property. Certain claimants, such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". General contractors and laborers for wages do not provide this notice. A "Preliminary Notice is not a lien against the property. Its' purpose is to notify you of persons who may have a right to file a lien against your property for debts that are not paid.

This is a Supplemental Inspection and Report to Report# 10925, dated 5-10-00, regarding Item(s)# 1B and 2A.

FINDING 1B1: Sections of subfloor was removed at owner's request to determine if fumigation will be needed. Evidence of wood boring beetle extending into inaccessible subfloor area and joists.  
RECOMMENDATION 1A1: Brace and mask areas of subfloor and joist. See Original Report on fumigation.  
SECTION 1.

FINDING 2A1: Shower flooring was removed. Fungus infection and damage noted in wall framing.  
RECOMMENDATION 2A1: Shower flooring was removed. Fungus infection and damage noted in wall framing.  
RECOMMENDATION 2A1: Remove and replace sections of wall framing. Remove all tile and replace with Dal tile D-100.  
\*note\* If owner or buyer wants to upgrade tile a price increase will be charged.  
SECTION 1.



# BOUEY PEST CONTROL

3639 4TH AVENUE  
SACRAMENTO CA 95817  
Tel (916) 733-0620 Fax (916) 733-0529 Alt

## AGREEMENT

No work will be performed until a signed copy of this agreement has been received.

Address of Property: 1408 7th Avenue  
City: Sacramento  
State/Zip: CA 95818

The inspection report of the company dated, 6/1/2000 bearing the Structural Pest Control Board Stamp Number, \_\_\_\_\_ is incorporated herein by reference as though fully set forth.

The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$ \_\_\_\_\_. This total amount is due and payable within Ten (10) days from completion repair work and/or chemical application.

### THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion, except for caulking, grouting or plumbing, which is guaranteed for a period of Ninety (90) days. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants or roof.

### THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The Owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

### ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

### NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control operator who contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his work or supplies, has a right to enforce a claim against your property. This means that after a court hearing your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your contractor in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". General contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

## ITEMS

SECTION 1 ITEM(S) #	1B1.....\$	120.00
	2A1.....\$	800.00
	TOTAL...\$	920.00

\*MINIMUM JOB PRICE...\$ 190.00\*

Property Owner: \_\_\_\_\_

Date: \_\_\_\_\_

Inspected By: Kath Paulsen

Date: \_\_\_\_\_

Owner's Agent: \_\_\_\_\_

Date: \_\_\_\_\_

No. 5664 P. 11

JUN 5 2000 1:53PM BOUEY PEST CONTROL