

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

P. 10 11

PERMIT NO.  
 B-24783.  
 DATE  
 2/3/48  
 ZONE

LOCATION 1541 - Santa Ynez  
 PURPOSE Erect new dwlg. & gar.  
 OWNER Joe M. Bishop.  
 ARCH'T.  
 CONT'R. H. Stude

VAL. 8000<sup>00</sup> =      STORIES 1      ROOMS 5      APTS.      SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	1034 <sup>00</sup>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
3/31/48	Frame insp. <i>B.F. Jones</i>
6/24/48	No Frame Insp. <i>O.E. Puckner</i>
6/24/48	Final Insp. "
	<p data-bbox="359 841 486 878">COMPLETE AND O. K.</p> <p data-bbox="1182 857 1312 882">INSPECTOR</p>