

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-14989</i>	LOCATION <i>138 - Tivoli Way.</i>
DATE <i>1/15/46</i>	PURPOSE <i>Erect new dwlg & garage</i>
ZONE	OWNER <i>jos. L. Binter.</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>685000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
--------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 10050'</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

. DATE.	CONDITION OF WORK-REMARKS
3/29/46	1 st Insp. Farms for New Drive & Garage ^{OK} M. Campbell
6/5/46	Frame Insp. D. E. Buckius
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>