

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>No. CHARGE PERMIT.</i>	LOCATION <i>2700 Riverside Blvd</i>		
DATE <i>APR. 11. 1931</i>	PURPOSE <i>Make repairs to floor in office Rest Rm.</i>	ROOMS	APTS.
ZONE <i>2-Family</i>	OWNER <i>MASONIC LAWN ASS'N.</i>	PHONE	
	ARCH'T		
	CONT'R <i>W. E. TRUESDALE</i>		
	VAL. <i>75⁰⁰</i>	STORIES <i>1</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION. OF WORK—REMARKS
7/14/31	Made drop of dry rot to Floor. Add Cornstarch

COMPLETED
AND O.K.

INSPECTOR