

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$40.00				
Lt. 66		TYPE BUILDINGS <del>R-219-227</del> R-111		
Southfield #1				
PERMIT NO.	LOCATION			
E-2688	7578 - Tamoshanter Way A-5			
DATE	PURPOSE			
Nov. 15-62	Const. dwelling & attached garage			
ZONE	OWNER			
R-1	McKeon Const. 1009 - J Street			
	ARCH'T			
	CONT'R	Owner	Same	447-1386
VAL. \$10,300.	STORIES	ROOMS	APTS.	480-gar. SIZE
	1	5		1,050 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	
FORM	11-31-62	Fuller		
JOIST	12-5-62	Fuller		
FRAME	1-17-63	Boylato		
SHEET ROCK	1-24-63	Boylato		
FINAL	3-18-63	Geo. Riehl	R	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-4-62	<p>pt plumbing not inspected.  Steel in fireplace not properly  stayed. Gaps on  pt not enough lap on clay pipe.</p>
1-16-63	<p>in place with backing on 78  sheet rock. Gaps 1x4 ribbon  missing. Tubs</p>
COMPLETE AND OK	INSPECTOR