

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-6965</i>	LOCATION <i>3806-West Land Park Dr.</i>			
DATE <i>11/12/40</i>	PURPOSE <i>Erect new dwlg for</i>			
ZONE <i>I</i>	OWNER <i>Roy Hess</i>			
	ARCH'T. <i>[Signature]</i>			
	CONT'R. <i>Owner</i>			
VAL. <i>6000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1400^{sq}</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3⁰⁰</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
11/19/40	1 ST INSP. Form in place OK A.W. Campbell
12/9/40	2 ND INSP. Frame " " OK A.W. Campbell
1/10/41	3 RD INSP. INT & EXT WORK OK A.W. Campbell
2/18/41	4 TH INSP. Ducts & Braces Completed OK
2/18/41	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR