

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

| | | | |
|---------------------------|--------------------------------|-------|-------|
| PERMIT NO. 4639 | LOCATION 4018-3 Ave | | |
| DATE | PURPOSE Resurf | ROOMS | APTS. |
| ISSUED | OWNER Ray Berman | PHONE | |
| ZONE 1929 | ARCH'T | | |
| SAC | INS'GR Stam Berg (4) | | |
| VAL. 19350 | STORIES | SIZE | |

| FOUNDATION | STORY | BSMT | 1 | 2 | 3 | ROOF | | | |
|------------|----------------------------|------|---|---|---|------|------------------|--|---------------|
| Ex Wall | Joints | | | | | | Chimneys | | Cement Tests |
| | Beams and Girders | | | | | | Fire Place | | |
| Int Wall | Studs and Columns | | | | | | Gas Water Heater | | |
| | Bridging Fire Stops | | | | | | Heater Closet | | |
| Piers | Fire Escape Stand Pipes | | | | | | Furnace | | Window Courts |
| | Metal Lath | | | | | | Boiler Room | | |
| | Stairs | | | | | | Elevator Shaft | | |