

B140 7142

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

| | | | | |
|----------------------|--|--------------------|-----------------|---------------|
| PERMIT NO. E-6636 | LOCATION 4031 - Parkside Court | | A-3 | |
| DATE Mar. 30-64 | PURPOSE Repair termite damage to dwelling. | | | |
| ZONE R-1 | OWNER Castro | Same | | |
| | ARCH'T 452-6655 | | | |
| | CONTR Paramount Pest Control 6405-Elvas Av | | | |
| VAL \$300. | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | 3-31-64 | Warrant | | |
| JOIST | | | | |
| FRAME | 3-31-64 | Warrant | | |
| SHEET ROCK | | | | |
| FINAL | 1-6-65 | <i>[Signature]</i> | | <i>cat</i> |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |