

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>No CHARGE</i>	LOCATION <i>2823 O St</i>		
DATE <i>Sept 25 1930</i>	PURPOSE <i>Re Shingle Roof of small Dwelling</i>	ROOMS	APTS.
ZONE <i>Multiple-Family</i>	OWNER <i>JOHN PETATTRA</i>	PHONE	
	ARCH'T		
	CONT'R <i>FRED ARNOLD</i>		
	VAL. <i>75⁰⁰</i>	STORIES <i>1</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joists						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE

CONDITION OF WORK—REMARKS

7/25/30

Re Shingling of Roof of Small Dwlg with
Redwood Shingles OK
A W Campbell

**COMPLETED
AND O.K.**

INSPECTOR

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No Charge</i>		LOCATION <i>2823 O. ST</i>			
PURPOSE <i>REPAIRS</i>		PURPOSE <i>Make Repairs to Front Porch steps of Drivg.</i>			
DATE <i>MAY 7, 1937</i>		OWNER <i>JOHN PETROTTA, 2823 O. ST.</i>		PHONES 	
ZONE <i>Middle- Family</i>		ARCH'T 			
		CONT-R <i>OWNER</i>			
VAL. <i>7500</i>		STORIES <i>1</i>	ROOMS 	APTS. 	SIZE
Light Shafts				Elevator Shafts	
Vent Shafts				Boiler Rooms	
Owner's Inspector				Sprinkler System	
Lath				Gas Vents	
Fire Escapes				Chimneys	
Stand Pipes				Skylights	

DATE	CONDITION OF WORK-REMARKS
5/2/32	Gave Owner this in Charge Permit for rebuilding and repairs to front porch. OK. Hal Campbell
	COMPLETE AND O. K. INSPECTOR

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No Change</i> (REPAIRS) DATE: MAY 5 1932 ZONE Multiple-Family	LOCATION: 2873 O. ST.
	PURPOSE: Make Repairs to Front Porch + Steps
	OWNER: JOHN PETROTTA
	ARCH'T: PHONES
CONT-R: OWNER	

VAL. 25 th	STORIES 1	ROOMS	APTS.	SIZE
-----------------------	-----------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
5/1/37.	Yare Corner No Change Permit for rebuilding front porch and steps. O.K.
	Owner to do painting. A.W. Campbell
	/
	/
5/2/37	COMPLETE AND O.K. Alden W. Campbell INSPECTOR