

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2158</i>	LOCATION <i>3932 — Miller Way</i>			
DATE <i>12/27/38</i>	PURPOSE <i>New dwlg. for</i>			
ZONE <i>2-Fam</i>	OWNER <i>Jim - J. Lunday</i>			
	ARCH'T.			
	CONT'R. <i>Universal Const. Co.</i>			
VAL. <i>3000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	BOILER ROOMS	<i>858⁰'</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 3"</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K. INSPECTOR