

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1735</i>	LOCATION <i>1427 - Joneight Way</i>			
DATE <i>8/13/38</i>	PURPOSE <i>New dwls. - garage</i>			
ZONE <i>2-Fam</i>	OWNER <i>Glen Mercer</i>			
	ARCH'T.			
	CON'TR. <i>R. H. Litter</i>			
VAL. <i>5736⁰⁰</i>	STORIES <i>2</i>	ROOMS	APTS	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>1496^{sq}</i>	
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
8/15/38	1 ST NSP Forms in place ^{OR} HW Campbell
9/22/38	2 ND NSP Form ^{OR} HW Campbell
	<p data-bbox="284 868 414 909">COMPLETE AND O. K.</p> <p data-bbox="1130 888 1267 909">INSPECTOR</p>