

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. 1977-A-	LOCATION 3260 - San Jose Way
DATE 9/5/34	PURPOSE Repair with epoxy paint floor
ZONE	OWNER Wright & Kimbrough
	ARCH'T.
	CONT'R Ideal Roof & Paint Co.

VAL. 11900	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
9/5/34	Re Roofing of Docks with Composite Shingles Completed - A.W. Campbell
9/5/34	COMPLETE AND O. K. <i>Alden W. Campbell</i> INSPECTOR