

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-7952</i>	LOCATION <i>518 - Robertson Way</i>
DATE <i>4/9/41</i>	PURPOSE <i>Erect new dwg.</i>
ZONE	OWNER <i>P. B. Roberson</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>3500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>932^{sq}</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
4/15/41	1 ST /NSP. Forms in place. <i>OK</i> <i>A.W. Campbell</i>
5/2/41	2 ND /NSP. France . . . <i>OK</i> <i>A.W. Campbell</i>
5/6/41	3 RD /NSP. INT. LITR. <i>OK</i> <i>A.W. Campbell</i>
5/26/41	4 TH /NSP. Duly & Garage Completed <i>OK</i>
5/26/41	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR </div>