

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-9014</b>	LOCATION <b>909 - 12<sup>TH</sup> ST.</b>			
DATE <b>8/29/41</b>	PURPOSE <b>Remodel Remick Bldg.</b>			
ZONE	OWNER <b>W. Wiseman</b>			
	ARCH'T.			
	CONT'R. <b>C. J. Hapkinson</b>			
VAL. <b>44,000<sup>00</sup></b>	STORIES <b>7</b>	ROOMS	APTS.	SIZE
LIGHT SHAFTS				ELEVATOR SHAFTS
VENT SHAFTS				BOILER ROOMS
OWNER'S INSPECTOR				SPRINKLER SYSTEM
LATH				GAS VENTS
FIRE ESCAPES				CHIMNEYS
STAND PIPES				SKYLIGHTS

DATE	CONDITION OF WORK - REMARKS
10/20/41	<sup>1st and</sup> 2 <sup>ND</sup> INSP. FRAME FOR 2 <sup>ND</sup> FLOOR <sup>Remodeling</sup> OK. A.H. Campbell
1/3/42	3 <sup>RD</sup> INSP. INT. LATH OK. A.H. Campbell
1/7/42	4 <sup>TH</sup> INSP. Remodeling of Bldg for Offices of Standard Oil Co. Appurtenances. O.K. A.H. Campbell.
1/7/42	COMPLETE AND O. K. <i>Alden H. Campbell</i>

INSPECTOR