

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 9623	LOCATION 2578 P St.	
	PURPOSE Repair	PHONES
DATE 6/29/32	OWNER J.P. Graneli	
ZONE Muth	ARCHT Stan R...	
VAL. 140 -	STORIES	ROOMS
		APTS.
		SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
7/9/32	Re-Roofing of Dwlg with Composition Shingles Completed OK H. Campbell
7/2/32	COMPLETE AND O. K. <i>William J. Campbell</i> INSPECTOR