

R145 214-118

Lots 1347 & 1348 **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$97.00
 Wright & Kimbrough **TYPE BUILDINGS** *R200 362-365 R1c*

| | |
|----------------------|---|
| PERMIT NO. E-7373 | LOCATION 1876 - Stockton Blvd. R-1 |
| DATE June 1-64 | PURPOSE Const. auto repair garage |
| | OWNER John Savarino Same |
| ZONE C-2 | ARCH'T 421-6178 |
| | CONTR Metal Engineering 8845-Elder Creek Rd. |

| | | | | |
|----------------|---------|-------|-------|-----------------------|
| VAL. \$30,700. | STORIES | ROOMS | APTS. | SIZE 6,160 sq. ft. |
|----------------|---------|-------|-------|-----------------------|

| | | | | |
|------------|----------------|----------------------|---------------------|----------------|
| INSP. | DATE | BLDG. TYPE v no. hr. | OCCUPANCY GROUP R-4 | PHONE (O) (C) |
| FORM | <i>8/5/64</i> | <i>Perlo</i> | | |
| JOIST | | | | |
| FRAME | <i>9/16/64</i> | <i>Perlo</i> | | |
| SHEET ROCK | <i>10-1-64</i> | <i>J. Barab</i> | | |
| FINAL | <i>12-8-64</i> | <i>Dana Felt</i> | | <i>not com</i> |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|---|
| 6-30-64 | slab poured without a slab inspection. Fuller |
| 7-7-64 | TILT UP PANELS OK. (2-3-4-6-7-8) Panels |
| 7-29-64 | P.T. NO ONE AROUND Panels |
| 7-31-64 | B SECTION FOOTINGS OK (Panels) |
| 8/12/64 9/16/64 | OK. frames - frames office only (Court) |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR