

N 218 7171

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00

## TYPE BUILDINGS

|                      |   |                        |                                      |
|----------------------|---|------------------------|--------------------------------------|
| PERMIT NO.<br>F-7543 | LOCATION 5801 - Ortega Street           |                        | A-4                                  |
| DATE<br>June 7-67    | PURPOSE<br>Const. 2 car detached garage |                        |                                      |
| ZONE<br>R-1          | OWNER<br>W. Fraser same                 |                        |                                      |
|                      | ARCH'T                                  |                        |                                      |
|                      | CONTR<br>Owner same 451-9461            |                        |                                      |
| VAL \$1,300.         | STORIES                                 | ROOMS                  | APTS. SIZE<br>528 sq. ft.            |
| INSP.                | DATE                                    | BLDG. TYPE<br>V-no hr. | OCCUPANCY GROUP<br>J-1 PHONE (O) (C) |
| FORM                 | 6-16-67                                 | Parsons                |                                      |
| JOIST                |   |                        |                                      |
| FRAME                | 7-10-67                                 | Const                  |                                      |
| SHEET ROCK           |   |                        |                                      |
| FINAL                | 1-24-68                                 | M. Callaway            |                                      |

| DATE               | SPECIAL CONDITIONS OF WORK—REMARKS |
|--------------------|------------------------------------|
| P. 3/1/67          | OK Historic Park Court             |
|                    |                                    |
|                    |                                    |
|                    |                                    |
|                    |                                    |
|                    |                                    |
|                    |                                    |
|                    |                                    |
|                    |                                    |
| COMPLETE<br>AND OK | INSPECTOR                          |