

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> 4577	<b>LOCATION</b> The Lincoln Bldg 21 Con Secs.	<b>2727 Du Blvd</b>	
<b>ISSUE</b> MAY 16 1923	<b>PURPOSE</b> Sample Restaurant	<b>ROOMS</b>	<b>APTS.</b>
<b>DATE</b>	<b>OWNER</b> J R Wilson	<b>PHONE</b> Lot - Fr. C.	
<b>BASEMENTS</b>	<b>ARCHT</b>	<b>CONTR</b> Clark Stanley 15-110	
<b>BUILDING DIVISION</b>	<b>VAL.</b> 350	<b>STORIES</b>	<b>SIZE</b>

FOUNDATION	STORY	BSMT	FLOOR			ROOF	Chimneys	Cement Tests
			1	2	3			
Ex Wall	Joints							
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging						Heater Closet	
	Fire Escape Stand Pipes						Furnace	Window Courts
Piers	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
5/22/19	Partial Frame Jap. in Remodeling of old Public Garage. Inv. J. R. Nelson instructions on method approved for Tensioning over Shop Structure A. W. Campbell <u>R. H. Ruster</u>
5/25/19	2 <sup>ND</sup> / NSP. Frame Remodeling; Store Front A. W. Campbell R. H. Ruster
5/15/19	3 <sup>RD</sup> / NSP. EXT. LATN IN PLACE OK A. W. Campbell R. H. Ruster
	COMPLETED AND O. K.
	INSPECTOR