

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-4576-</i>	LOCATION <i>2816 - Regina Way.</i>
DATE <i>7/16/36</i>	PURPOSE <i>Erect new residence -</i>
ZONE	OWNER <i>F. R. Nicklin -</i>
	ARCH'T.
	CONTR. <i>C. C. Ruby</i>

VAL. <i>4400⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE <i>See Plan</i>
-------------------------------	---------------------	-------------------	-------	-------------------------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 176⁰⁰</i>
VENT SHAFTS		BOILER ROOMS	<i>@ 350</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
7/18/36	1 ST INSP. FORMER PLACE ^{OK} RW Campbell
8/20/36	2 ND INSP. FRAME ^{OK} RW Campbell
9/3/36	3 RD INSP. INT + EXT. LATH ^{OK} RW Campbell
11/9/36	4 TH INSP. DWELL + GARAGE Completed
	Issued Final Insp. + Cert. of Occupancy
	Street cleaned up OK RW Campbell
11/9/36	<p>COMPLETE AND O. K. <i>Alfred H. Campbell</i> INSPECTOR</p>