

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-1107</i>	LOCATION <i>916 - 4<sup>th</sup> Street</i>
DATE <i>11/30/40</i>	PURPOSE <i>Remodel Bldg for Fong Fong Ass'n</i>
ZONE <i>Gen Com</i>	OWNER <i>Fong Fong</i>
	ARCH'T.
	CONT'R. <i>Don Tatti</i>

VAL.	STORIES	ROOMS	APTS.	SIZE
<i>4300</i>	<i>1</i>			
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
12/2/30	Made Partial Job of Remodeling Bldg. Contractor installed additional braces in Roof Trusses Rem. roof interior. Partially R/W Complete
12/17/30	2 <sup>ND</sup> WSP. Frame in place <sup>OR</sup> R/W Complete
12/19/30	3 <sup>RD</sup> WSP. INT. LATH & PARTIAL R/W Complete
12/27/30	2 <sup>ND</sup> WSP. Frame for Allow. in Entrance Steps etc
12/31/30	3 <sup>RD</sup> WSP. INT. LATH, MAIN FLOOR — R/W Complete
1/3/31	4 <sup>TH</sup> WSP. Remodeling Int. including main R/W Complete for 2 <sup>ND</sup> story
1/3/41	COMPLETE AND O. K. <i>W. J. ...</i> INSPECTOR