

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-3323</i>	LOCATION <i>3015- San Carlos Way.</i>			
DATE <i>9/17/35</i>	PURPOSE <i>Repairs Alter to residential</i>			
ZONE	OWNER <i>Margaret Steiger</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>2500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="340 833 476 875">COMPLETE AND O. K.</p> <p data-bbox="1186 849 1323 875">INSPECTOR</p>