

R288 F120

Lot 1172 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$74.00				
Glenbrook Unit No. 11 TYPE BUILDINGS R-282 F-58-62 Plans				
PERMIT NO.		LOCATION		
G-8252		88 - Mossglen Circle A-1 (52)		
DATE		PURPOSE		
9-8-70		Construct dwelling & garage MP 1004LC		
ZONE		OWNER		
R-1		Wilbrook, Inc, 2777 Alvarado St, San Leandro		
		ARCH'T		
		Leandro		
		CONTR		
		Besco Builders, Same as owner		
VAL. \$19,800.		STORIES	ROOMS	APTS. 475-gar. SIZE 1,297-sq.ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 383-9315
FORM	9-11-70	Callaway		
JOIST				
FRAME	10-15-70	Callaway		
SHEET ROCK	10-30-70	Miller		
FINAL	11-19-70	M. Callaway		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
9-18-70	Asst. slat <span style="float: right;">C. Williams</span>

COMPLETE  
AND OK

INSPECTOR