

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-8597</i>	LOCATION <i>1821 - Pkt. (REAR)</i>			
DATE <i>6/30/44</i>	PURPOSE <i>Remodel apartments</i>			
ZONE	OWNER <i>E. S. Brasler Martin</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>1000</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
7/15/41	1 ST WSP. Foundations & Pkg already in place
10/10/41	2 ND WSP. Frame for 2- 2 Room Apts on lower floor for Apts House on rear of lot O.K.
	H.W. Campbell
2/16/41	3 RD WSP. INT DATA. owner used 3/8" Rock bath with 20 gauge lead fire over same
	O.K. H.W. Campbell
7/4/42	4 TH WSP. Apts in lower floor completed. O.K.
3/4/42	COMPLETE AND O. K. Alden W. Campbell
	INSPECTOR.